



June 28, 2016

Dear Valued Customer:

You are receiving this letter because our records indicate you purchased a Honda Pioneer 1000 Snorkel Kits, Part # SNORK-H1000P. The original SNORK-H1000P kit purchased used a bellow that does not meet our high standards of quality. In some cases, the bellow will expand beyond the bellows ability and cause it to rupture.

The repair kit is Part # 58A with complete instructions on how to replace the bellows with the new vent line. Do not ride your unit until the new update is installed.

We apologize for the inconvenience of updating the snorkel kit for your SNORK-H1000P. Customer satisfaction and safety are top priority at High Lifter. Should you have any additional questions regarding this kit update, please give us a call at 800-699-0947

Thank you,

Brian Smith

Head of Engineering

High Lifter Products